

AUDI P1139: LONG TERM FUEL TRIM ADD. FUEL, BANK 2 SYSTEM TOO RICH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	No

What Does The Audi P1139 Code Mean?

Engine started, battery voltage must be at least 11.5v, all electrical components must be off, the ground between the engine and the chassis must be well connected, the exhaust system must be properly sealed between the catalytic converter and the cylinder

What Are The Potential Causes Of The Audi P1139 Code?

- Air intake system leaking, vacuum hoses leaking or damaged
- Air leaks located after the MAF sensor mounting location
- EGR valve sticking, EGR diagramleaking, or gasket leaking
- EVAP vapor recovery system has failed
- Excessive fuel pressure, I

Reference Sources

- Audi of America, 2012, [Technical Service Bulletin](#).
- Audi of America, 2013, [Technical Service Bulletin](#).
- Audi of America, 2015, [Technical Service Bulletin](#).
- Audi of America, 2014, [Technical Service Bulletin](#).