

AUDI P1560: MAXIMUM ENGINE SPEED EXCEEDED

OVERVIEW

Severity	:	<div></div> High
DIY Difficulty Level	:	<div></div> Advanced
Repair Cost	:	\$400-\$850
Can I Still Drive?	:	No

What Does The Audi P1560 Code Mean?

This code indicates the condition that engine is running, the ECM has detected that the maximum engine speed had been attained.

What Are The Potential Causes Of The Audi P1560 Code?

Below are some potential causes of this DTC:

- Throttle valve control module has failed
- Throttle valve control module's circuit has shorted or is open
- The ECM has failed
- General engine damage

Reference Sources

- [Audi A4 Avant 95-01 Service Repair Manual](#), page 57.
- Omnitek Engineering Corp., 2006, [Diagnostic Trouble Code \(DTC\) Guide for Omnitek ECM 64A/66A/88A](#), page 140.