

AUDI P1565: IDLE SPEED CONTROL THROTTLE POSITION LOWER LIMIT NOT ATTAINED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$850
Can I Still Drive?	:	No

What Does The Audi P1565 Code Mean?

Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, coolant temperature at least 80-degrees Celcius and the throttle valve must not be damaged or dirty; and the ECM detected the signal from the Throttle Position Valve Module to the ECM detected was erratic, non existent or unreliable (too high or too low).

What Are The Potential Causes Of The Audi P1565 Code?

- Alternator failed
- ECM failed
- Fuses blown or open circuits
- Clean Throttle Valve Control Module
- Accelerator cable not adjusted properly
- Idle speed control throttle failed
- Wire connections to relay carrier and ground connection of ECM may have shorted

Reference Sources

[Audi A4 Avant 95-01 Service Repair Manual](#), page 57.