7.0011 1040. HVI		CONTROL MODULE ERROR	(LLI KOWI)
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$800-\$1500	
Can I Still Drive?	:	No	

## What Does The Audi P1640 Code Mean?

Ignition on, the ECM detected a control module malfunction (software). To achieve optimal anti-theft protection for the vehicle, an anti-theft immobilizer is installed. The anti-theft immobilizer is a system for enabling and locking the Engine Control Module (ECM).

So that this system cannot be circumvented, it is necessary to perform adaptation of the anti-theft immobilizer using the Vehicle Diagnostic and Information System VAS 5052 in the On Board Diagnostic (OBD) function.

The great availability of equipment options makes it necessary to adapt the Engine Control Module (ECM) to the vehicle (e. g. throttle valve control module or cruise control system). This "writing" function is not possible with the generic scan tool.

## What Are The Potential Causes Of The Audi P1640 Code?

- Engine Control Module (ECM) has failed
- Voltage supply for Engine Control Module (ECM) has shorted

## **Reference Sources**

Audi A4 Avant 95-01 Service Repair Manual, page 61.

