AUDI P1780: TORQUE WITHDRAWAL FAULTY OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$100-\$200 Can I Still Drive? : Yes (Short-term only)

What Does The Audi P1780 Code Mean?

Malfunction Criteria and Threshold Value: Comparison with nominal values-switch off and U < 2.1 V; switch on and U > 1.6 V.

What Are The Potential Causes Of The Audi P1780 Code?

Below are some potential causes of this DTC:

- TCS circuit open or shorted in the wiring harness
- TCS not cycled during the self-test
- TCS is damaged or failed, or the ECM has failed
- Check ATF level
- Mechanical malfunction in transmission

Reference Sources

Audi P1780, DTCDECODE.

