RESET ERROR (BANK 2)		
OVERVIEW		
Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	: \$350-\$500	

## What Does The BMW P1009 Code Mean?

After 1.5ms and the DME and VVT are active, it is detected that the sensor is not properly resetting.

## What Are The Potential Causes Of The BMW P1009 Code?

- Plug contact problem at Pin 6 on sensor
- Oil in plug at sensor
- Replace sensor
- Repair gaskets

## **Reference Sources**

BMW P1009, DTCDECODE.

