PARITY ERROR (BANK 2)			
OVERVIEW			
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$350-\$500	

What Does The BMW P1010 Code Mean?

After 12ms and the DME and VVT are active, it is detected that the sensor is not properly communicating. The plug is defective on the sensor or there is an open circuit

What Are The Potential Causes Of The BMW P1010 Code?

- Plug contact problem at Pin 6 on sensor
- Oil in plug at sensor
- Replace sensor
- Repair gaskets

Reference Sources

BMW P1010, DTCDECODE.

