BMW P1014: VALVETRONIC (VVT) REFERENCE SENSOR PARITY ERROR (BANK 1) OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$100-\$200 Can I Still Drive? : Yes (Short-term only)

What Does The BMW P1014 Code Mean?

This code indicates that after 12ms and the DME and VVT are active, it is detected that the sensor is not properly communicating. The plug is defective on the sensor or there is an open circuit.

What Are The Potential Causes Of The BMW P1014 Code?

Below are some potential causes of this DTC:

- Plug contact problem at Pin 6 on sensor
- Oil in plug at sensor
- Replace sensor
- Repair gaskets

Reference Sources

BMW P1014, DTCDECODE.

