

BMW P1015: VALVETRONIC (VVT) REFERENCE SENSOR GRADIENT ERROR (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The BMW P1015 Code Mean?

After 9ms and the DME and VVT are active, it is detected that the sensor has a gradient violation/identity, causing a reading of implausible sensor data. The plug is defective on the sensor or there is an open circuit.

What Are The Potential Causes Of The BMW P1015 Code?

Replace sensor

Reference Sources

[BMW P1015](#), DTCDECODE.