

BMW P1061: VALVETRONIC (VVT) LIMP HOME REQUEST RPM AND CHARGE LIMITATION (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes

What Does The BMW P1061 Code Mean?

After 3000ms the charge difference between the two banks (caused by other VVT faults) lead to an rpm charge limit.

What Are The Potential Causes Of The BMW P1061 Code?

Resolve the primary fault.

Reference Sources

[BMW P1061](#), DTCDECODE.