

BMW P1062: VALVETRONIC (VVT) LIMP HOME REQUEST FULL STROKE POSITION NOT REACHED (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes

What Does The BMW P1062 Code Mean?

After 3000ms the eccentric angle fails to close at the full stroke position. Other VVT fault issues maximum stroke command but the position is not reached.

What Are The Potential Causes Of The BMW P1062 Code?

Resolve the primary fault.

Reference Sources

[BMW P1062](#), DTCDECODE.