BMW P1068: VALVETRONIC (VVT) REFERENCE SENSOR RESET ERROR (BANK 2)		
OVERVIEW		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

## What Does The BMW P1068 Code Mean?

After 1.5ms and the DME and VVT are active, it is detected that the sensor is not properly resetting.

## What Are The Potential Causes Of The BMW P1068 Code?

- Plug contact problem at Pin 6 on sensor
- Oil in plug at sensor
- Replace sensor
- Repair gaskets

## **Reference Sources**

BMW P1068, DTCDECODE.

