

BMW P1069: VALVETRONIC (VVT) REFERENCE SENSOR PARITY ERROR (BANK 2)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The BMW P1069 Code Mean?

This code indicates that after 12ms and the DME and VVT are active, it is detected that the sensor is not properly communicating. The plug is defective on the sensor or there is an open circuit.

What Are The Potential Causes Of The BMW P1069 Code?

Below are some potential causes of this DTC:

- Plug contact problem at Pin 6 on sensor
- Oil in plug at sensor
- Replace sensor
- Repair gaskets

Reference Sources

[BMW P1069](#), DTCDECODE.