

BMW P1070: VALVETRONIC (VVT) REFERENCE SENSOR GRADIENT ERROR (BANK 2)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The BMW P1070 Code Mean?

After 9ms and the DME and VVT are active, it is detected that the sensor has a gradient violation/identity, causing a reading of implausible sensor data. The plug is defective on the sensor or there is an open circuit.

How Can You Fix The BMW P1070 Code?

Replace sensor

Reference Sources

[BMW P1070](#), DTCDECODE.