BMW P1076: VALVETRONIC (VVT) OVERLOAD PROTECTION ECU TEMPERATURE HIGH INPUT (BANK 1)		
OVERVIEW		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$300-\$500
Can I Still Drive?	:	Yes

What Does The BMW P1076 Code Mean?

After the ignition is on for 45ms, the ECU temperature was recorded as too high.

What Are The Potential Causes Of The BMW P1076 Code?

- Sticking in VVT mechanicals, pinion gear, etc.
- Loose sensor
- Sensor servo motor has short circuit

Reference Sources

BMW P1076, DTCDECODE.

