BMW P1079: VALVETRONIC (VVT) OVERLOAD PROTECTION (BANK 1)

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$300-\$500

Can I Still Drive? : Yes

What Does The BMW P1079 Code Mean?

After the ignition is on for 45ms, the temperature was recorded as too high.

What Are The Potential Causes Of The BMW P1079 Code?

- Sticking in VVT mechanicals, pinion gear, etc.
- Loose sensor
- Sensor servo motor has short circuit

Reference Sources

BMW P1079, DTCDECODE.

