

What Does The BMW P1329 Code Mean?

Engine started, vehicle driven at 2000rpm for 3 seconds or to a temperature of 40 degrees Celsius, and the DME detected the Knock Sensor 1 (KS1) signal was too low or not recognized by the DME.

What Are The Potential Causes Of The BMW P1329 Code?

- Knock sensor circuit is open
- Knock sensor is loose (tighten to 20 NM)
- Contact between the knock sensor and cylinder block is dirty, corroded or greasy
- Knock sensor circuit is shorted to ground, or shorted to power
- Knock sensor is damaged

Reference Sources

BMW P1329, DTCDECODE.

