SHORT TO GROUND			
		OVERVIEW	
Severity	:	M	edium
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$120-\$500	
Can I Still Drive?	:	Yes	

## What Does The BMW P1507 Code Mean?

Engine running the DME detected that the idle air control valve signal was intermittent.

## What Are The Potential Causes Of The BMW P1507 Code?

- Fuel delivery unit connector is loose or not attached
- Fuse 18 cause a short to the transfer fuel pump or the O2S
- Fuel pump has failed
- Fuel pump relay circuit is shorted to ground, B+ or is open
- Fuel Pump (FP) Relay not activated

## **Reference Sources**

BMW P1507, DTCDECODE.

