

BMW P1530: CAMSHAFT CONTROL CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	No

What Does The BMW P1530 Code Mean?

Engine started and driven at an engine speed of more than 400rpm; and the DME detected the camshaft timing exceeded the calibrated levels. The valve timing did not change from the current valve timing or it remained fixed during the testing.

What Are The Potential Causes Of The BMW P1530 Code?

- Fuel pump has failed
- CPS circuit is open, shorted to ground or shorted to power

Reference Sources

[BMW P1530](#), DTCDECODE.