

BMW P1535: DIFFERENTIATED INTAKE MANIFOLD COIL TEMPERATURE LIMIT VALUE EXCEEDED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$400-\$800
Can I Still Drive?	:	Yes

What Does The BMW P1535 Code Mean?

This fault stems from the 4.8L-N62 equipped with an infinitely adjustable control of induction system. The temperature of the coil has exceeded the predetermined limits.

What Are The Potential Causes Of The BMW P1535 Code?

- Faulty controller
- Faulty coil

Reference Sources

[BMW P1535](#), DTCDECODE.