

BMW P1642: THROTTLE VALVE ADAPTATION STOP DUE TO ENVIRONMENTAL VALUES

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$600-\$850
Can I Still Drive?	:	Yes

What Does The BMW P1642 Code Mean?

Engine started, and the battery voltage is greater than 7 volts, this fault is only diagnosed during the throttle valve's adaptation phase. Environmental conditions for throttle valve adaptation were not present and adaptation aborted.

What Are The Potential Causes Of The BMW P1642 Code?

There is no action required

Reference Sources

[BMW P1642](#), DTCDECODE.