

BMW P1758: SHIFT SOLENOID B

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$500
Can I Still Drive?	:	No

What Does The BMW P1758 Code Mean?

The shift solenoid valve is not receiving a signal after 50ms of operation.

What Are The Potential Causes Of The BMW P1758 Code?

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

Reference Sources

[BMW P1758](#), DTCDECODE.