

BMW P1763: SHIFT SOLENOID C SHORT TO GROUND

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$500
Can I Still Drive?	:	No

What Does The BMW P1763 Code Mean?

The shift solenoid valve is shorting to ground after 50ms of operation.

What Are The Potential Causes Of The BMW P1763 Code?

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

Reference Sources

[BMW P1763](#), DTCDECODE.