

CADILLAC P1122: TP SENSOR CIRCUIT INTERMITTENT LOW INPUT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Cadillac P1122 Code Mean?

Key on or engine running; and the PCM detected an intermittent low voltage condition on the TP sensor signal circuit (less than 0.16v) for 1 second during the test.

What Are The Potential Causes Of The Cadillac P1122 Code?

- TP sensor signal circuit is shorted to ground (intermittent fault)
- TP sensor VREF circuit is open or grounded (intermittent fault)
- TP sensor is damaged or has failed (possible intermittent short)
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).