

CADILLAC P1281: TP SENSORS MISMATCH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Cadillac P1281 Code Mean?

DTCs [P0606](#), [P1517](#), or [P1518](#) are not set. The ignition switch is in the crank or run position. The ignition voltage is greater than 5.23 volts.

What Are The Potential Causes Of The Cadillac P1281 Code?

- Inspect the TAC module connectors for signs of water intrusion. If water intrusion occurs, multiple DTCs may set without any circuit or component conditions found during diagnostic testing.
- When the TAC module detects throttle movement with a DTC P1

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).