

CADILLAC P1359: IGNITION COIL GROUP 1 CONTROL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	No

What Does The Cadillac P1359 Code Mean?

Key on or engine running; then during PCM power-up mode, the PCM detected an open circuit or short to power condition on the IC control circuit for Ignition Coil Group 1 (cylinders 1, 4, 6 and 7) for less than 1 second during the CCM test.

What Are The Potential Causes Of The Cadillac P1359 Code?

- IC control circuit for Coil Group 1 is open or shorted to power
- ICM power or ground circuit is open or has high resistance
- ICM is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).