

CADILLAC P1360: IGNITION COIL GROUP 2 CONTROL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	No

What Does The Cadillac P1360 Code Mean?

Engine started; then during PCM power-up mode, the PCM detected an open circuit or short to power condition on the IC control circuit for Ignition Coil Group 2 (cylinders 2, 3, 5 and 8) for less than 1 second during the CCM test.

What Are The Potential Causes Of The Cadillac P1360 Code?

- IC control circuit for Coil Group 2 is open or shorted to power
- ICM power or ground circuit is open or has high resistance
- ICM is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).