

CADILLAC P1361: IGNITION CONTROL MODULE LOW INPUT

OVERVIEW

Severity	:	 Medium
DIY Difficulty Level	:	 Advanced
Repair Cost	:	\$50-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1361 Code Mean?

Engine cranking, and the PCM detected 84 revolutions of the crankshaft occurred without detecting any Ignition Control circuit pulses during the CCM test.

What Are The Potential Causes Of The Cadillac P1361 Code?

Below are some potential causes of this DTC:

- IC timing control circuit is shorted to ground or shorted to power
- IC module has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).