

CADILLAC P1571: TRACTION CONTROL SYSTEM - PWM CIRCUIT NO FREQUENCY

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$320-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1571 Code Mean?

DTC P1602 not set, engine started, engine speed over 500 rpm for 20 seconds, Traction Control active (not failed), and the PCM did not detect a PWM signal on the Desired torque circuit for 3 seconds.

What Are The Potential Causes Of The Cadillac P1571 Code?

Below are some potential causes of this DTC:

- TCS desired torque circuit is open or shorted to ground
- TCS desired torque circuit is shorted to system power (B+)
- EBCM has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).