

CADILLAC P1629: THEFT DETERRENT FUEL ENABLE SIGNAL NOT RECEIVED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$130-\$480
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P1629 Code?

A GM SPO replacement engine control module (ECM) is in a functional state to learn the password from the theft deterrent control module. If the theft deterrent control module is replaced, the ECM must be placed in password learning mode to relearn the new procedure.

Reference Sources

- GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).
- GM, 2012, [Service Bulletin - No Crank, Multiple Warning Telltales On, Trans Shifts Hard](#).
- GM, 2013, [No Crank Multiple Warning Telltales On Trans Shifts Hard](#).
- GM, 2015, [No Crank Multiple Warning Telltales On Trans Shifts Hard](#).
- GM, 2015, [No Crank - Multiple Warning Telltales On - Trans Shifts Hard](#).
- GM, 2015, [No Crank Key Stuck In Ignition Lock Cylinder Multiple ECM Codes And U1000 Set In Class 2 Modules](#).