

What Are The Potential Causes Of The Cadillac P1637 Code?

DTC P1637 and a low battery charge may be caused by a generator fault. Such as a shorted output diode, malfunctioning regulator, open or shorted rotor, or open sense lead. Refer to engine electrical for further information and generator diagnosis.

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

