

## CADILLAC P1743: THROTTLE POSITION SIGNAL INVALID DATA RECEIVED

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

### What Does The Cadillac P1743 Code Mean?

Key on or engine running; and the TCM detected a throttle position pulsewidth signal that was more than 96% during the CCM test. The TCM receives throttle position data from the PCM. This data is part of the PWM PCM data signal to the PCM.

### How Can You Fix The Cadillac P1743 Code?

- Perform the Powertrain Onboard Diagnostics System Check
- Refer to the repair information for DTC P0120

### Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.