

CADILLAC U1048: NO COMMUNICATION WITH REAR WHEEL STEERING CONTROL MODULE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1048 Code Mean?

Key on, and a message from a learned ID number was not detected for the five seconds. Modules on the Class 2 circuit monitor for data communications during vehicle operation.

What Are The Potential Causes Of The Cadillac U1048 Code?

- RWSCM Class 2 circuit is open, shorted to ground or to B+
- RWSCM ignition power circuit has a high resistance condition
- RESCM main ground circuit(s) has a high resistance condition
- RESCM (module) may have failed and is pulling the circuit low

Reference Sources

[Cadillac U1048](#), DTCDECODE.