

## CHEVROLET P1188: ENGINE OIL PRESSURE SENSOR HIGH INPUT

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chevrolet P1188 Code Mean?

Engine running over 30 minutes, and the PCM detected the Engine Oil Pressure (EOP) sensor indicated less than -23°F for 4.5 seconds. The ECT and EOP sensors should be within a few degrees after sitting overnight.

### What Are The Potential Causes Of The Chevrolet P1188 Code?

- EOP sensor signal circuit is open, or the EOP sensor ground circuit is open
- EOP sensor is damaged or it has failed (possible open circuit)
- PCM has failed

### Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.