CHEVROLET P1400: COLD START INJECTION MONITORING		
		OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$650
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1400 Code Mean?

Engine is in Exhaust Warm-up mode. DTC runs continuously when the above condition exists.

Post Injection has been prohibited for 100 continuous engine revolutions for any one of the following reasons:

- Post injection events do not increase the diesel oxidation catalyst temperature to a calibrated level within a given time.
- A post injection event overlaps the pre-injection event of the next cylinder in the firing order.
- The ECM detects a post injection energizing error.

Reference Sources

Chevrolet Volt Hybrid DTC - OBDG01 HYBRID Diagnostics Document, page 147.

