

What Does The Chevrolet P1760 Code Mean?

The components are powered and ignition voltage is greater than 9.0 volts and less than 18 volts. There is a loss of TCM supply voltage before the drive cycle data is saved.

What Are The Potential Causes Of The Chevrolet P1760 Code?

Inspect the wiring for poor electrical connections at the TCM. Look for the following conditions:

- A bent terminal
- A backed-out terminal
- A damaged terminal
- Poor terminal tension
- A chafed wire
- A broken wire inside the insulat

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

