

CHEVROLET P179A: AUXILIARY TRANSMISSION FLUID PUMP OVERSPEED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$1500
Can I Still Drive?	:	No

What Does The Chevrolet P179A Code Mean?

The vehicle is ON or the power inverter module is awake.

An auxiliary transmission fluid pump motor speed of greater than 6500 RPM has been detected.

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 823.