

## CHEVROLET P1875: 4WD LOW SWITCH CIRCUIT ELECTRICAL (ELECTRIC SHIFT, 4.3L ONLY)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### How Can You Fix The Chevrolet P1875 Code?

Inspect the wiring for poor electrical connections at the VCM. Inspect the wiring for poor electrical connections at the transmission 20-way connector. Look for the following conditions:

- A bent terminal
- A backed out terminal
- A damaged terminal

### Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.