CHEVROLET P1E23: AUXILIARY TRANSMISSION FLUID PUMP CONTROL MODULE RANDOM ACCESS MEMORY		
		OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$1500
Can I Still Drive?	:	No

## **What Does The Chevrolet P1E23 Code Mean?**

The vehicle is ON. The system voltage is 8-18 V.

The control module has detected an internal malfunction, or a control module was not programmed after replacement.

## **Reference Sources**

Chevrolet Volt Hybrid DTC - OBDG01 HYBRID Diagnostics Document, page 837.

