

CHEVROLET P1E37: AUXILIARY TRANSMISSION FLUID PUMP INVERTER HIGH TEMPERATURE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$1500
Can I Still Drive?	:	No

What Does The Chevrolet P1E37 Code Mean?

Conditions for setting the DTC: The vehicle is ON and propulsion is active. DTC P1E36 is not set. The pump inverter temperature sensor is greater than 98°C (208°F).

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 833.