

## CHEVROLET U1096: NO COMMUNICATION WITH INSTRUMENT PANEL CLUSTER

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Chevrolet U1096 Code Mean?

Key on, and a message from a learned ID number was not detected for the five seconds. Modules on the Class 2 circuit monitor for data communications during vehicle operation.

- IPC Class 2 circuit is open, shorted to ground or to B+
- IPC ignition power circuit has a high resistance condition
- IPC main ground circuit(s) has a high resistance condition
- IPC (module) may have failed and is pulling the circuit low

### Reference Sources

[Chevrolet U1096](#), DTCDECODE.