

CHRYSLER B10E9: BLOWER MOTOR CONTROL CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$700
Can I Still Drive?	:	Yes

What Does The Chrysler B10E9 Code Mean?

With the ignition on. If the Totally Integrated Power Module (TIPM) detects an excessive current draw on the (C70) Blower Motor Control circuit for 20 micro seconds when blower motor operation is requested.

What Are The Potential Causes Of The Chrysler B10E9 Code?

- (C7) Blower Motor Control Circuit Shorted To Ground
- Blower Motor
- TIPM

Reference Sources

[Chrysler B10E9](#), DTCDECODE.