CHRYSLER B18BB: WINDOW CONTROL CIRCUIT LOW		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	•	\$100-\$400
Nopuli Cost	•	1.00 7.00
Can I Still Drive?	:	Yes

What Does The Chrysler B18BB Code Mean?

Whenever the module is awake. When the fused ignition switch output circuit to the power window switch is pulled to ground for over 10 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B18BB Code?

- (F981) fused ignition switch output circuit short to ground
- Window switch shorted
- Totally integrated power module (TIPM)

Reference Sources

Chrysler B18BB, DTCDECODE.

