

## CHRYSLER B1E4E: 3RD ROW SEAT LEFT STOW/TAILGATE POSITION SENSOR CIRCUIT LOW

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$100-\$300                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Chrysler B1E4E Code Mean?

If sensor voltage is below a specified range this DTC will set.

### What Are The Potential Causes Of The Chrysler B1E4E Code?

- (P318) left seat stow position sensor supply circuit
- Left power rear folding seat stow motor
- Folding seat module (FSM)

### Reference Sources

[Chrysler B1E4E](#), DTCDECODE.