

What Does The Chrysler C1477 Code Mean?

The Drivetrain Control Module (DTCM) detects an overheat condition due to excessive difference in speed across the Transfer Case from extreme driving conditions (Mud, Sand, Snow, 2WD Chassis dynamometer, etc).

What Are The Potential Causes Of The Chrysler C1477 Code?

- Driving conditions
- Drivetrain 5 volt supply circuit shorted to ground
- Drivetrain control module (DTCM)

Reference Sources

<u>Chrysler C1477</u>, DTCDECODE.

