

CHRYSLER C157B: FRONT AXLE LEVEL SENSOR CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$30-\$80
Can I Still Drive?	:	Yes

What Does The Chrysler C157B Code Mean?

The HIDT detects the Headlamp Leveling Sensor Front Signal circuit is to low.

What Are The Potential Causes Of The Chrysler C157B Code?

- (L960) headlamp leveling sensor signal shorted to ground
- (I960) headlamp leveling sensor signal open or high resistance
- (I961) headlamp leveling sensor return 5 volt supply circuit shorted to ground
- (I961) headlamp leveling sensor return 5 volt supply circuit open or high resistance
- (I961) headlamp leveling sensor 5 volt supply circuit shorted to (I962) headlamp leveling sensor return circuit
- Front headlamp leveling sensor
- High intensity discharge translator (HIDT) module

Reference Sources

[Chrysler C157B](#), DTCDECODE.