

What Does The Chrysler P127A Code Mean?

With the ignition on. Battery voltage greater than 10.4 volts. The TIPM has detected on overcurrent condition in the Starter Control circuit. One Trip Fault. Three good trips to turn off the MIL

What Are The Potential Causes Of The Chrysler P127A Code?

- (T40) STARTER RELAY OUTPUT CIRCUIT EXCESSIVE RESISTANCE
- (T40) STARTER RELAY OUTPUT CIRCUIT SHORTED TO GROUND
- (T750) STARTER RELAY OUTPUT CIRCUIT EXCESSIVE RESISTANCE
- (T750) STARTER RELAY OUTPUT CIRCUIT SHORTED TO GROUND
- STARTER RELAY
- STARTER
- TIPM

Reference Sources

Chrysler P127A, DTCDECODE.

