

CHRYSLER U1108: ADDITIONAL CAN B ECU DETECTED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Chrysler U1108 Code Mean?

Continuously. The Totally Integrated Power Module (TIPM) detects an additional CAN B module and requires a reconfiguration.

What Are The Potential Causes Of The Chrysler U1108 Code?

Additional module added/removed from the can B bus network

Reference Sources

[Chrysler U1108](#), DTCDECODE.