

DODGE P1793: TORQUE MANAGEMENT REQUEST CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$45-\$850
Can I Still Drive?	:	No

What Does The Dodge P1793 Code Mean?

Key on and the TCM did not detect any signals on the Torque Management Request circuit

What Are The Potential Causes Of The Dodge P1793 Code?

- Extremely low battery (system) voltage
- Torque management request circuit is open, shorted to ground or shorted to system power (i. e. , the TRD circuit has failed) or the TCM has failed

Reference Sources

[Dodge P1793](#), DTCDECODE.