NOT AVAILABLE			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$100-\$1000	
Can I Still Drive?	:	No	

What Does The GMC P1380 Code Mean?

The vehicle speed is greater than 8 km/h (5 mph). The engine speed is less than 8,192 RPM. The engine load is less than 60 percent. Engine misfire is detected and DTC <u>P0300</u> sets with the MIL illuminated. DTCs P1380 and <u>P1381</u> run continuously when the above conditions are met.

What Are The Potential Causes Of The GMC P1380 Code?

- The electronic brake control module (EBCM) sends a message to the ECM indicating that a failure has occurred in the EBCM.
- Engine misfire is detected and DTC P0300 sets with the MIL illuminated.

Reference Sources

Technical Service Bulletin PIP5094 for P1380 - General Motors

